CLAMP METERS

400A AC/DC True RMS Clamp Meter

- *True RMS.*
- *Backlit display and worklight.*
- *Magnetic mount and lead storage.*
- *Non-contact voltage tester.*
- *Analog bar graph.*
- *Measures DC Current.*

True RMS
DC Current

KLEIN TOOLS®

Pictured: CL2000

Cat. No.	Weight (lbs.)
CL2000	.67

All dimensions are in inches and (millimeters) except where indicated.