



# ELLIOTT ELECTRIC SUPPLY

We Deliver...Lower Cost, Quality Products, & Personal Service

2310 N. Stallings Dr.  
75964-0000, TX Nacogdoches  
Phone: 936-569-7941  
Fax: 936-560-4685



## **BOX120 Box Conn SGL Weave 1.2-1.5 Dia**

*Pass & Seymour/Legrand*

Catalog Number	BOX120
Manufacturer	Pass & Seymour/Legrand
Description	Wide Range, Straight Male, Dust Tight Grips. 1 1/2-Inch NPT, 1.200-1.500-Inch.
Weight per unit	0.8188 (lbs/each)
Product Category	Cable & Cord Grips

### **Features**

Cable Size	NPT Size: 1-1/2; Cable Dia. Range: 1.200-1.500
Cable Type	Various Types of Electrical Conductor/Cable
load	Strain Relief Grips are designed to prevent tension from being transferred to junctions and terminals on electrical cord, cable and conduit, therefore providing a more secure electrical structure.

### **Descriptions**

Construction	Various Types of Pulling, Support and Strain Relief Grips
Description	BOX CONN SGL WEAVE 1.2-1.5 DIA
extra long description	P&S BOX120 BOX CONN SNG WEAVE 1.2-1
Long Description	Wide range, Straight male, Dust tight grips. 1 1/2-inch NPT, 1.200-1.500-inch.
Product Type	Box Conn SNG Weave 1.2-1.5dia
Special Features	Wide range grips are recommended for use in wiring of enclosures, power boxes, machine tools, and power centers. Includes insulated bushing.

### **Manufacturer Information**

Brand	Pass and Seymour
GTIN	00785007996203
Manufacturers Part Number	BOX120
UPC	785007996203

### **Taxonomies, Classifications, and Categories**

Category Description	CORD CONNECTORS & CORD GRIPS
Type	Flexcor® Strain Relief Grip - Wide Range, Straight Male, Dust Tight

### **Packaging**

Carton	1
Package	8
Weight Per each	0.8188



# ELLIOTT ELECTRIC SUPPLY

We Deliver...Lower Cost, Quality Products, & Personal Service

2310 N. Stallings Dr.  
75964-0000, TX Nacogdoches  
Phone: 936-569-7941  
Fax: 936-560-4685

## Uses, Certifications, and Standards

Application	Industrial
Capacity	Various Cable Diameter Ranges
Mounting	Consult the Factory for Mounting Recommendations
standard	UL/CSA Approval (consult factory)